

Alubrite 6450

Aluminum Cleaner & Brightener

Description

Super concentrated blend of acids and surface cleaners designed to restore aluminum. Works at ambient temperature.

Recommended Application

1

Alubrite is used at 20% concentration.

2

Spray, brush, or wipe surface.

Alubrite may also be used in a water bath at 20% concentration. Wait at least one minute for best results.

3

Rinse thoroughly with water.

Benefits

- Super concentrated
- Works at ambient temperatures
- Removes oxidation

Health & Safety

Please see SDS for complete health and safety information.

12336 Emerson Dr. | Brighton, MI 48116 | 248-587-5600
Fax: 248-587-5606 | www.gccdatasheets.com